

Dairyland Farm LLC
5420 Gauthier Rd
New Franken, WI 54229



September 28, 2020

1. Dairyland Farm LLC
5420 Gauthier Rd
New Franken, WI 54229
(920) 866-2336
2. Photo 2
3. Duration of the spill was first discovered at 10:30am on September 23, 2020. Cleanup efforts were started at 10:31am on September 23, 2020. At 12:00pm on September 23, 2020 cleanup efforts was concluded.
4. The cause of the spill was a brand new hose ripped. Dairyland Farm LLC is working with the manufacture to make sure it meets 200 PSI run and 660-PSI burst pressure.
5. First step stop the flow of manure 10:31am September 23,2020. Second step used a chisel plow at 10:35am on September 23, 2020. Third step we used a skid steer and a vacuum tank to clean up and install 2 dams for safety to protect waterway at 10:40am on September 23, 2020.
6. Photos 3, 4, 5
7. Approximately 550 gallons were recovered after we flushed the area with clean water.
8. 550 gallons of a mixture of water and digested manure was put into WSF 2.
9. Photo 4.
10. Test new hoses using only clean water to make sure they meet 200 PSI run and 660 PSI burst pressure.

Thank you!

Dairyland Farm LLC

2

Sec. 14-T24N-R22E

Brown County



Field

Acres

Dan 1 Dan 2



4

Dam being removed



⑤

Area after Cleanup



③

Dam being Installed

